

RADIUS MEASURING TOOL FOR CONVEX SURFACES

Copy this drawing to a piece of wood, plywood or plastic, and carve out along the curved outlines.
Put the edge of the tools over the curve of the surface to be measured. Turn the tool until you find the radius with the best fit to the curve of the measured object.

