

RADIUS MEASURING TOOL FOR CONVEX SURFACES

COPY THIS DRAWING TO A PIECE OF WOOD,
PLYWOOD OR PLASTIC AND CARVE ALONG
THE CURVED OUTLINES.
PUT THE EDGE OF THE TOOL ON THE
SURFACE YOU WISH TO MEASURE.
TURN THE TOOL UNTIL YOU FIND THE BEST
FITTING RADIUS TO THE MEASURED
OBJECT.

